



Step 1.



Step 2.


Install Metal Shell onto Panel

Tighten Panel Nut, Recommended tightening, torque : 6-8 kgf- cm





Step 3.


Install Mating O-Ring onto Housing and then install Housing into already mounted Shell.



Step 4.



Panel Cut-out



**WÜRTH
ELEKTRONIK**
MORE THAN
YOU EXPECT

Würth Elektronik eiSos GmbH & Co. KG
EMC & Inductive Solutions
Max-Eyth-Str. 1
74638 Waldenburg
Germany
Tel. +49 (0) 79 42 945 - 0
www.we-online.com
eiSos@we-online.com

CREATED

MDa

CHECKED

CPo

DESCRIPTION

Assembly instructions

WR-CIRCM12

Panel PCB Angled Metal - 643 270 100 3xx & 643 280 100 3xx

REVISION

001.001

STATUS

Valid

DATE

2022-02-28

BUSINESS UNIT

eiCan